THREAD REPAIR



Spark Plug Thread Repair

14 mm Tapered Spark **Plug Thread Repair Kit** SKU **141511** 25647



STORE STOCK

- Can Be Used to Repair Both Taper Seat and Gasket Type Spark Plug Assemblies
- Three Insert Lengths are Available to Accommodate Most Spark Plug Reaches
- Positive Mechanical Locking Feature Means the Insert Will Never Come Out
- The Piloted Reamer Tap Means No Drilling is Necessary and Perfect Alignment of the Tapped Hole

14 mm Tapered Spark Plug Inserts

SKU **141512**

25648 STORE STOCK

- 6 Pieces in Three Lengths M14 1.25
- Drill Size: 14.25 mm; 9/16"

Plug Thread Repair System SKU **557108**

25643 STORE STOCK

- Replaces Threads for 14 mm
- Kit Includes: 3 Thread Inserts, Thread Installer Tool and Thread Tap
- Sizes: M14 1.25
- Not for Tapered Spark Plugs

14 mm Thread Inserts SKU **557140**

25644 STORE STOCK

- 10 Pieces in Sizes M14 1.25 x 3/8",1/2", 3/4"
- Drill Size: 14.25 mm; 9/16"
- Not for Tapered Spark Plugs

M12 - 1.25 O=MTOOLS **Spark Plug Thread Repair** Kit SKU **789141**

25640 • Kit Includes: 3 Thread Inserts, Thread Installer Tool and Thread Tap

- 6 0 Designed for Rethreading in All Materials Such as Alloys, Steels, Plastics, Magnesium, etc. • Specified for Military, Aviation and Other
- Critical Usage • Inserts are Made From High Quality 18-8 Stainless Steel Wire with a Diamond Shaped Cross Section Wound to the
- Shape of a Spring Thread • Not for Tapered Spark Plugs

Drain Plug Repair

Drain Plug Repair Kit Cal-Yan SKU **818569** 7999

CAL38400



- Drain Plug Repair Kit Contains a Drill, Counter Bore, Tap, Driver, Guide and (5) 12 mm Inserts
- Repairs Stripped Drain Plugs without Leakage and Allows Users to Use Original Plug Instead

5 Pack Drain Plug Inserts

SKU **850539** 👖 🕦 **99** CAL384-5



FIX-A-THRED

Thread Repair

3 Piece Internal/External **Thread Repair Set** SKU **343362**

NES1015 • Includes the NES1A, NES21 and NES22 Restores Inch or Metric, Right or Left Handed Fastener Threads



Oxygen Sensor Thread Repair Kit

SKU **010134** FIX38189-1

- No Need to Replace Exhaust Manifold
- Pilot Nose Tap Provided
- Easy and Quick to Use, Repairs in Minutes

FIX-A-THRED

Metric Head Bolt Thread Repair Kit SKU **010131**

FIX35119S

- Applications Cadillac®, Honda®, Toyota® and Other Imports
- Extended Reach for Deep Threads

516468*

OF MINORS

• Longer Length (33 mm) Inserts for Maximum Thread Engagement

Replacement Inserts

25611



OEM TOOLS

9.99

COEM TO COURT

Metric **Thread Repair Kits**

25626

25628

25632



M6 - 1

M8 - 1.25

M10 - 1.5

| Replacement |
|--------------|
| Inserts |
| *STORE STOCK |

25627

25629

25633



M10 - 1.5



7.99

| *STORE ST | ГОСК | *STORE STOCK | | | | | |
|-----------|----------|----------------|-------|----------|----------|----------------|-------|
| SKU | Part No. | Size | Price | SKU | Part No. | Size | Price |
| 557009* | 25602 | UNC 1/4" - 20 | 22.99 | 557116* | 25603 | UNC 1/4" - 20 | 6.99 |
| 557017 * | 25604 | UNC 5/16" - 18 | 22.99 | 557124 * | 25605 | UNC 5/16" - 18 | 6.99 |
| 557090* | 25606 | UNC 3/8" - 18 | 22.99 | 557132 * | 25607 | UNC 3/8" - 16 | 7.99 |
| 516464* | 25608 | UNC 7/16" - 14 | 29.99 | 516465* | 25609 | UNC 7/16" - 14 | 7.99 |

29.99

Drill Bits and Extractor Sets

6 Piece Spiral Flute **Screw Extractor Set**

SKU **099277** 24374

SKU **099281**

24375

516472*

516474*

516477 *

• Extractors: Ex-1. Ex-2.

Ex-3, Ex-4, Ex-5 and Ex-6 M2 Steel • Comes in a Vinyl Pouch

Screw Extractor Set

• Contains Sizes from 1/8" - 13/32" in 1/32" Increments

• Can Be Used with Hand

Sockets and Wrenches

· Constructed of High Carbon

Steel for Strength Under

• Aggressive Left Hand Spiral

Stressful Conditions

Design Provides Extra

Gripping Power

10 Piece Multi-Spline

29.99

29.99

29.99

10 Piece Bolt **Extractor Set**

516473 *

516475 *


516478 *

SKU **231204** 25467 STORE STOCK









• Set Includes Extractors Size: #1, #2, #3, #4, #5 and Bits: 5/64", 7/64", 5/32", 1/4" and 19/64"





- REG. \$39.99 • Extractors: Ex-1, Ex-2, Ex-3, Ex-4 and Ex-5 • Left Hand 135 Degree Split Point Cobalt
- Drill Bit Sizes: 5/64", 7/64", 5/32", 1/4" and 19/64"
- Aggressive Left Hand Spiral Design for Extra Gripping Power • 135 Degree Split Point Left Hand Drill Bits Cut Through
- Pilot Point Starts on Contact and Eliminates Bit Walking

Offer Good Through March 31, 2017 - While Supplies Last

25 Piece Screw **Extractor/Drill and Guide Set** SKU **099215** 24376

UNC 1/2" - 13

• Can Be Used on Thread Sizes 5 mm to 16 mm

• Comes in a Blow Mold Case

SAE Thread Repair Kits

25610

516467 *

• Turns Broken Fastener Out and Permits Highest Torque without Expansion

OEM TOOLS

3 Piece Double Edge Bolt and **Screw Extractor Set**

SKU **042367**

KNP9R4719033

- Contains Sizes 1-3 in a Plastic Tube • Tip Has Built-In Center Punch
- No Additional Tool Required

5 Piece Double Edge Bolt and Screw **Extractor Set**

SKU **042353** KNP9R4719043

Ford Spark Plug Extractor Set

- Contains Sizes 1-5 in a Plastic Tube • Tip Has Built-In Center Punch
- No Additional Tool Required



Broken Spark Plug Remover

SKU **489173**

LIS65600

Ford Triton 3 Valve

• Includes a Unique Porcelain Pusher Tool and a Tapered Left Hand Thread

Spark Plug without Leaving the

Porcelain in the Engine Cylinder

Remover for Removing the Broken

Master Screw Extractor/Drill Bit Set SKU **099258** 24377

35 Piece

UNC 1/2" - 13

• Full Range of Spiral and Multi-Spline Extractors for Removing the Toughest Bolts and Screws From 3/32" to 15/16"

• OEM 135° Split Point Left Hand Cobalt Drill Bits, Start Easy and Drill the Toughest



Spark Plug Thread Repair for Ford Triton

Ford Spark Plug Porcelain Extractor Set

SKU **104290**

2099



 In Some Cases the Porcelain Will Break Off in the Sleeve and Will Need to Be Extracted in Order for the 24201 to Function Effectively

• Unlike Other Tools That Tell You to Push the Porcelain Through the Sleeve (Ford Says Specifically Not to Do This) This Tool Adheres to the Porcelain Using a Special Adhesive and Then Allows a User to Extract the Broken Porcelain From the Sleeve

Loctite 60800 5 mL Replacement Adhesive SKU **248475** 24204

Replacement Pins SKU **248476** 24205



Ford Triton Plug-Saver® Kit

Extractor to Make Sure the Job is Done Right

SKU **094873** FIX98140T

SKU **104286**

24201

 Designed to Specifically Repair the Spark Plug Ports in 4.6, 5.4 and 6.8 Ford Triton Engines

Specially Machined Guide Works with Extra Long Tap and

Repairs Worn, Damaged Threads

Works to Extract Frozen and

Sleeves in 2004 to Present

Ford Triton Engines

- Self Cutting Tap
- Includes Tap, Tool and Eight Inserts in a Sturdy Case



FIX-A-THRED

Inserts (Pack of 8) SKU **110263** FIX98149P



Carkin

Ford Cylinder Repair Set

SKU **104283** 24200

Comes with Instructional Video

- Repair of Ford Triton Modular Engines is Going to Be a Large Issue in the Next 5 Years (Ford Triton Engines 1996 2003 Have a Problem with Spark Plug Thread Erosion, Resulting in Spark Plug Threads Coming Out During Tune-Up or Shooting Spark Plugs Out During Operation)
- Current Repair Takes About 10 Labor Hours, This Tool Cuts Time to 30 Minutes to an Hour
- Works on Ford 4.6, 5.4, 6.8 V10 Engines
- Individual Inserts Available as Part Number 24203. The Patented Replacement
- Set Includes: Instruction Sheet, DVD, (6) Inserts, Reamer Tap, Drill Bit, Expanding Tool and Air Blower Accessory Assembly
- Insert is a Permanent Fix That Does Not Have to Be Replaced with Every Tune-Up. • Patented Guide Makes Drilling and Tapping in a Straight Line Easy



Ford Triton 14 mm x 1.25 Repair Insert **2**/199 each SKU 104287 24203

Taper on the Inside of the Insert That Seats the Spark Plug

• Alloy Steel Insert - Not Aluminum • Seals Perfectly and Prevents Any Loss of Compression



OEM TOOLS

Ford Triton 16 mm x 1.5 3 Valve Insert SKU **396658**

• Note: THIS IS NOT the Replacement Insert for the Triton 2 Valve Kit

Ford Triton 3 Valve Set SKU **343388**

CAL39300 • Application: 2004-2008 Ford 4.6 and 5.4 3 Valve

Engines That Have Spark Plugs That are M16 x 1.5 • Includes (8) Inserts

